Flood Control Project Maintenance Levee Inspections

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83	09/16/2016 09/16/2016	Tariq Chechi

LM Start		Rating **	Α	Issue No.		2	
LM End		Issue Type +	Ма	Location *	N/A		
Category Earthen Levee				GPS La	atitud	le/Longitude	
Calegory				Start		End	
Item Operations & Maintenance Manuals					0		0
					0		0
DWR ID DWR_NA0014_01_s _ 2013_2							
Comment Code							
Inspector Comment							
The LMA completed flood fight training in 2014.							

No Photos

LM Start		Rating **	Α	Issue No.		3	
LM End		Issue Type +	Ма	Location *		N/A	
Catagony	GPS Latitude/Longitude						
Category				Start		End	
Item Emergency Supplies &				0		0	
пеш	Equipment				0		0
DWR ID	DWR ID DWR_NA0014_01_s _ 2013_3						
		Comn	nent Cod	de			
Inspector Comment							
The LMA has adequate flood fight supplies and equipment.							

No Photos

Flood Control Project Maintenance Levee Inspections

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83	09/16/2016 09/16/2016	Tariq Chechi

LM Start		Rating **	Α	Issue No.		6	
LM End		Issue Type +	Ma	Location *		N/A	
Category	Earthen L	evee		GPS La	atitud	de/Longitude	
Calegory			Start		End		
Flood Preparedness & Training				0		0	
item				0		0	
DWR ID DWR_NA0014_01_s _ 2013_6							
		Comn	nent Cod	le			
Inspector Comment							
There is no O&M Manual for M&T Ranch.							

No Photos

LM Start	0.00	Rating **	Α	Issue No.		5		
LM End	0.00	Issue Type +	Ma	Location *		CR		
Category Earthen Levee				GPS Latitude/Longitude				
Calegory				Start		End		
Item Crown Surface / Depressions / Rutting				39.6675	34°		0	
				-121.9596	00°		0	
DWR ID DWR_ST0014_01_f _ 2016_5								
Comment Code								
0.4 4 1 1								

C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.

Inspector Comment

The crown is adequately maintained.



No Photos

LM Start	0.00	Rating **	М	Issue No.		1	
LM End	0.09	Issue Type +	Ma	Location *		WS	
Category Earthen Levee			GPS Latitude/Longitude				
Category	JOI y			Start		End	
Item	Vegetation			39.6675	34°	39.666836°	
item			-121.9596	12°	-121.960897°		
DWR ID DWR_NA0014_01_s _ 2012_1							
Comment Code							

V4: Elderberries are blocking visibility and flood fight capability.

Inspector Comment

* Location + Issue Type Ma : Maintenance Deficiancy
Ob : Design & System Obsolescence LS : Land Side N/A: Not Applicable A : Acceptable M : Minimally Acceptable N : Not Inspected/Rated WS: Water Side C : Corrected A/W : Acceptable but Monitor & Maintain U : Unacceptable En: Enforcement

Flood Control Project Maintenance Levee Inspections

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83	09/16/2016 09/16/2016	Tariq Chechi

-								
LM Start	0.00	Rating **	М	Issue No.		4		
LM End	0.09	Issue Type +	Ma	Location *		LS		
Category Earthen Levee				GPS Latitude/Longitude				
				Start		End		
Vegetation			39.6677	° 80′	39.666983°			
пеш			-121.959817°		7° -121.960997°			
DWR ID	DWR ID DWR_NA0014_01_s _ 2012_4							
		Comn	nent Cod	de				
V4 : Elderk	perries are	blocking visib	ility and	flood fight	сара	bility.		
		Inspecto	or Comm	nent				

No Photos

WS : Water Side
CR : Crown

N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain + Issue Type
Ma: Maintenance Deficiancy
Ob: Design & System Obsolescence
En: Enforcement